

INDUSTRIAL COMPONENT DATA

DILM32-XWG 239375 Y7-239375 EATON ELECTRIC Cable routing, for DILM7-M32

Brand: EATON - MOELLER | Manufacturer Part Number: DILM32-XWG



Manufacturer	EATON - MOELLER
MPN / Reference	DILM32-XWG
Catalog number	Y7-239375
Category	Accessories/spare parts for low-voltage switch technology
Minimum order	1 Pcs
Document ID	EO-CFBD68CBAB
Generated	2026-08-04

Product Overview

Cable routing, for DILM7-M32

DILM32-XWG

Eaton Moeller® series DILM Cable routing, for DILM7-M32

Cable raceway for contactors

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path EATON - MOELLER > Contactors up to 170A

Additional Product Information

General specifications

Product Name Eaton Moeller® series DILM cable routing Catalog Number 239375 Model Code DILM32-XWG EAN 4015082393755 Product Length/Depth 31.5 mm Product Height 23 mm Product Width 9 mm Product Weight 0.002 kg

Certifications CSA

UL Category Control No.: NLRV

CSA File No.: 012528

CE

UL Recognized

IEC/EN 60947-4-1

UL File No.: E36332

CSA-C22.2 No. 14-05

UL 508

CSA Class No.: 3211-05 General

Accessory/spare part type Connecting bridge Product category Accessories Design verification

Equipment heat dissipation, current-dependent P_{vid} 0 W Heat dissipation capacity P_{diss} 0 W Rated operational current for specified heat dissipation (I_n) 0 A 10.2.2 Corrosion resistance Meets the product standard's requirements. 10.2.3.1

Verification of thermal stability of enclosures Meets the product standard's requirements. 10.2.3.2 Verification of resistance of insulating materials to normal heat Meets the product standard's requirements. 10.2.3.3 Resist. of insul. mat. to abnormal heat/fire by internal elect. effects Meets the product standard's requirements. 10.2.4 Resistance to ultra-violet (UV) radiation Meets the product standard's requirements. 10.2.5 Lifting Does not apply, since the entire switchgear needs to be evaluated. 10.2.6 Mechanical impact Does not apply, since the entire switchgear needs to be evaluated. 10.2.7 Inscriptions Meets the product standard's requirements. 10.3 Degree of protection of assemblies Does not apply, since the entire switchgear needs to....

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / DILM32-XWG with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.