

INDUSTRIAL COMPONENT DATA

DILM32-XIP2X 118855 Y7-118855 EATON ELECTRIC Cover, opening DILM1738 connection, (8unit)

Brand: EATON - MOELLER | Manufacturer Part Number: DILM32-XIP2X



Manufacturer	EATON - MOELLER
MPN / Reference	DILM32-XIP2X
Catalog number	Y7-118855
Category	Accessories/spare parts for low-voltage switch technology
Minimum order	1 Pcs
Document ID	EO-E1675CBE61
Generated	2026-08-05

Product Overview

Cover, opening DILM1738 connection, (8unit)

DILM32-XIP2X

Eaton Moeller® series DILM Cover, connection opening DILM17-38, (8unit)

Mountable busbar tag shroud without tools

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path **EATON - MOELLER > Contactors up to 170A**

Additional Product Information

General specifications

Product Name Eaton Moeller® series DILM terminal cover Catalog Number 118855 Model Code DILM32-XIP2X EAN 4015081170043 Product Length/Depth 7 mm Product Height 36 mm Product Width 34 mm Product Weight 0.006 kg

Certifications UL/CSA certification not required General

Accessory/spare part type Cover Product category Accessories Used with DILM17

DILM25

DILM32

DILM38

DILMP32

DILMP45

DILL...

DILMF8

DILMF11

DILMF14

DILMF17

DILMF25

DILMF32 Climatic environmental conditions

Ambient operating temperature - min -25 °C Ambient operating temperature - max 60 °C Design verification

Equipment heat dissipation, current-dependent P_{vid} 0 W Heat dissipation capacity P_{diss} 0 W Rated operational current for specified heat dissipation (I_n) 0 A 10.2.2 Corrosion resistance Meets the product standard's requirements. 10.2.3.1

Verification of thermal stability of enclosures Meets the product standard's requirements. 10.2.3.2 Verification of resistance of insulating materials to normal heat Meets the product standard's requirements. 10.2.3.3 Resist. of insul. mat. to abnormal heat/fire by internal elect. effects Meets the product standard's requirements. 10.2.4 Resistance to ultra-violet (UV) radiation Meets the product standard's requirements. 10.2.5 Lifting Does not apply, since the entire switchgear needs to be evaluated. 10.2.6 Mechanical impact Does not apply, since the entire switchgear needs to be evaluated. 10.2.7 Inscriptions Meets the product standard's requirements. 10....

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / DILM32-XIP2X with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.