

INDUSTRIAL COMPONENT DATA

DILA-XHICV11 276529 XTCEXFALCC11 EATON ELECTRIC

Auxiliary contact module, 1N/O early+1N/C late, surface moun..

Brand: EATON - MOELLER | Manufacturer Part Number: DILA-XHICV11



Manufacturer	EATON - MOELLER
MPN / Reference	DILA-XHICV11
Catalog number	XTCEXFALCC11
Category	Auxiliary contact block
Minimum order	1 Pcs
Document ID	EO-9A14CCE4AE
Generated	2026-08-03

Product Overview

Auxiliary contact module, 1N/O early+1N/C late, surface mounting, spring clamp connection

Auxiliary contact block 1 NOA + 1 NOR Front mounting Connection

Auxiliary contact module, 2 pole, Ith= 16 A, 1 N/OE, 1 NCL, Front fixing, Spring-loaded terminals, DILA, DILM7 - DILM38

Auxiliary contact module, Function: for standard applications, 2 pole, Connection technique: Spring-loaded terminals, Rated operational current AC-15 220 V 230 V 240 V: Ie= 4 A, Rated operational current AC-15 380 V 400 V 415 V: Ie= 4 A, Contacts N/OE: NO early-make: 1 N/OE, Contacts NCL=NC late-break: 1 NCL, Mounting type: Front fixing, For use with: DILA(C)..., DILM(C)7..., DILM(C)9..., DILM(C)12..., DILM(C)15..., DILM(C)17..., DILM(C)25..., DILM(C)32..., DILM38..., DILMP20..., DILMP32..., DILMP45..., DILL..., DILMF8..., DILMF11..., DILMF14..., DILMF17..., DILMF25..., DILMF32..., Type: Front mounting auxiliary contact , Code number and version of combination Distinctive number: 51, 42, 33

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path EATON - MOELLER > KDIL Accessories

Additional Product Information

EL-Nummer (Norway)4110270Auxiliary contact module, 2 pole, Ith= 16 A, 1 N/OE, 1 NCL, Front fixing, Spring-loaded terminals, DILA, DILM7 - DILM38Auxiliary contact module, Function: for standard applications, 2 pole, Connection technique: Spring-loaded terminals, Rated operational current AC-15 220 V 230 V 240 V: Ie= 4 A, Rated operational current AC-15 380 V 400 V 415 V: Ie= 4 A, Contacts N/OE: NO early-make: 1 N/OE, Contacts NCL=NC late-break: 1 NCL, Mounting type: Front fixing, For use with: DILA(C)..., DILM(C)7..., DILM(C)9..., DILM(C)12..., DILM(C)15..., DILM(C)17...,

DILM(C)25..., DILM(C)32..., DILM38..., DILMP20..., DILMP32..., DILMP45..., DILL..., DILMF8..., DILMF11..., DILMF14..., DILMF17..., DILMF25..., DILMF32..., Type: Front mounting auxiliary contact, Code number and version of combination Distinctive number: 51, 42, 33 Delivery program

Accessories Auxiliary contact modules Function for standard applications Number of poles 2 pole Connection technique Spring-loaded terminals Rated operational current Conventional free air thermal current, 1 pole Open at 60 °C [Ith] 16 AAC-15220 V 230 V 240 V [Ie] 4 AAC-15380 V 400 V 415 V [Ie] 4 A Contacts N/OE: NO early-make 1 N/OENCL=NC late-break 1 NCL Mounting type Front fixing Contact sequence For use with DILA(C)...

DILM(C)7...
DILM(C)9...
DILM(C)12...
DILM(C)15...
DILM(C)17...
DILM(C)25...
DILM(C)32...
DILM38...
DILMP20...
DILMP32...
DILMP45...
DILL...
DILMF8...
DILMF11...
DILMF14...
DILMF17...
DILMF25...
DILMF32... Type Front mounting auxiliary contact Code number and version of combination Distinctive number 51 with basic dev...

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / DILA-XHICV11 with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.