

INDUSTRIAL COMPONENT DATA

DILM95-XSP(208V60HZ) 229991 Y7-229991 EATON ELECTRIC

Replacement coil alternating current for DILM80-95

Brand: EATON - MOELLER | Manufacturer Part Number: DILM95-XSP(208V60HZ)



Manufacturer	EATON - MOELLER
MPN / Reference	DILM95-XSP(208V60HZ)
Catalog number	Y7-229991
Category	Coil for relay
Minimum order	1 Pcs
Document ID	EO-0CC7C871DC
Generated	2026-08-05

Product Overview

Replacement coil alternating current for DILM80-95

DILM95-XSP(208V60HZ)

Eaton Moeller® series DILM Replacement coil, Tool-less plug connection, 208 V 60 Hz, AC, For use with: DILM80, DILM96

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path **EATON - MOELLER > Contactors up to 170A**

Additional Product Information

General specifications

Product Name Eaton Moeller® series DILM replacement coil Catalog Number 229991 Model Code

DILM95-XSP(208V60HZ) EAN 4015082299910 Product Length/Depth 48.65 mm Product Height 71.3 mm Product Width 63.2 mm Product Weight 0.155 kg Certifications UL 60947-4-1

CSA

CSA Class No.: 3211-04

CE

CSA-C22.2 No. 60947-4-1-14

IEC/EN 60947-4-1

UL

UL Category Control No.: NLDX

CSA File No.: 2389068

UL File No.: E29096 General

Accessories Individual coils Product category Accessories Voltage type AC Magnet system
Rated control supply voltage (Us) at AC, 50 Hz - min 0 V Rated control supply voltage (Us) at AC, 50 Hz - max 0 V Rated control supply voltage (Us) at AC, 60 Hz - min 208 V Rated control supply voltage (Us) at AC, 60 Hz - max 208 V Rated control supply voltage (Us) at DC - min 0 V Rated control supply voltage (Us) at DC - max 0 V Design verification
10.2.2 Corrosion resistance Meets the product standard's requirements. 10.2.3.1 Verification of thermal stability of enclosures Meets the product standard's requirements. 10.2.3.2 Verification of resistance of insulating materials to normal heat Meets the product standard's requirements. 10.2.3.3 Resist. of insul. mat. to abnormal heat/fire by internal elect. effects Meets the product standard's requirements. 10.2.5 Lifting Does not apply, since the entire switchgear needs to be evaluated. 10.2.6 Mechanical impact Does not apply, since the entire switchgear needs to be evaluated. 10.2.7 Inscriptions Meets the produc...

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / DILM95-XSP(208V60HZ) with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.