

INDUSTRIAL COMPONENT DATA

DILM95-XSP(48V50HZ) 229985 Y7-229985 EATON ELECTRIC

Replacement coil alternating current for DILM80-95

Brand: EATON - MOELLER | Manufacturer Part Number: DILM95-XSP(48V50HZ)



Manufacturer	EATON - MOELLER
MPN / Reference	DILM95-XSP(48V50HZ)
Catalog number	Y7-229985
Category	Coil for relay
Minimum order	1 Pcs
Document ID	EO-8653A60E2C
Generated	2026-08-03

Product Overview

Replacement coil alternating current for DILM80-95

DILM95-XSP(48V50HZ)

Eaton Moeller® series DILM Replacement coil, Tool-less plug connection, 48 V 50 Hz, AC, For use with: DILM80, DILM95 Replacement coil, Connection technique: Tool-less plug connection, Actuating voltage: 48 V 50 Hz, Voltage AC/DC: AC, For use with: DILM80, DILM95

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path EATON - MOELLER > Contactors up to 170A

Additional Product Information

General specifications

Product Name Eaton Moeller® series DILM replacement coil Catalog Number 229985 Model Code DILM95-XSP(48V50HZ)

EAN 4015082299859 Product Length/Depth 48.65 mm Product Height 71.3 mm Product Width 63.2 mm Product Weight

0.155 kg Certifications CSA

IEC/EN 60947-4-1

UL Category Control No.: NLDX

UL File No.: E29096

UL

CSA Class No.: 3211-04

UL 60947-4-1

CSA File No.: 2389068

CSA-C22.2 No. 60947-4-1-14

CE General

Accessories Individual coils Product category Accessories Voltage type AC Magnet system

Rated control supply voltage (Us) at AC, 50 Hz - min 48 V Rated control supply voltage (Us) at AC, 50 Hz - max 48 V Rated control supply voltage (Us) at AC, 60 Hz - min 0 V Rated control supply voltage (Us) at AC, 60 Hz - max 0 V Rated control supply voltage (Us) at DC - min 0 V Rated control supply voltage (Us) at DC - max 0 V Design verification

10.2.2 Corrosion resistance Meets the product standard's requirements. 10.2.3.1 Verification of thermal stability of enclosures Meets the product standard's requirements. 10.2.3.2 Verification of resistance of insulating materials to normal heat Meets the product standard's requirements. 10.2.3.3 Resist. of insul. mat. to abnormal heat/fire by internal elect. effects Meets the product standard's requirements. 10.2.5 Lifting Does not apply, since the entire switchgear needs to be evaluated. 10.2.6 Mechanical impact Does not apply, since the entire switchgear needs to be evaluated. 10.2.7 Inscriptions Meets the product s...

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / DILM95-XSP(48V50HZ) with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.