

INDUSTRIAL COMPONENT DATA

DILM32-XVB 281227 Y7-281227 EATON ELECTRIC Connector, for DILA, DILM732

Brand: EATON - MOELLER | Manufacturer Part Number: DILM32-XVB



Manufacturer	EATON - MOELLER
MPN / Reference	DILM32-XVB
Catalog number	Y7-281227
Category	Accessories/spare parts for low-voltage switch technology
Minimum order	50 Pcs
Document ID	EO-3848306645
Generated	2026-08-04

Product Overview

Connector, for DILA, DILM732

DILM32-XVB

Eaton Moeller® series DILM Connector, for DILA, DILM7-32

Simply use clips to connect contactor to assemblies

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path **EATON - MOELLER > Contactors up to 170A**

Additional Product Information

General specifications

Product Name Eaton Moeller® series DILM connector Catalog Number 281227 Model Code DILM32-XVB EAN 4015082812270 Product Length/Depth 15.6 mm Product Height 5.6 mm Product Width 22 mm Product Weight 1.22 g

Certifications CE

IEC/EN 60947-4-1

CSA Class No.: 3211-05

UL File No.: E36332

UL Category Control No.: NLRV

UL Recognized

CSA

CSA-C22.2 No. 14-05

CSA File No.: 012528

UL 508 Features & Functions

Functions For mechanically linking contactor relays in combinations General

Accessory/spare part type Connecting bridge Product category Accessories Climatic environmental conditions

Ambient operating temperature - min -25 °C Ambient operating temperature - max 60 °C Design verification

Equipment heat dissipation, current-dependent P_{vid} 0 W Heat dissipation capacity P_{diss} 0 W Rated operational current for specified heat dissipation (I_n) 0 A 10.2.2 Corrosion resistance Meets the product standard's requirements. 10.2.3.1

Verification of thermal stability of enclosures Meets the product standard's requirements. 10.2.3.2 Verification of resistance of insulating materials to normal heat Meets the product standard's requirements. 10.2.3.3 Resist. of insul. mat. to abnormal heat/fire by internal elect. effects Meets the product standard's requirements. 10.2.4 Resistance to ultra-violet (UV) radiation Meets the product standard's requirements. 10.2.5 Lifting Does not apply, since the entire switchgear needs to be

evaluated. 10.2.6 Mechanical impact Does not apply, sin...

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / DILM32-XVB with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.