

INDUSTRIAL COMPONENT DATA

DILM65-XIP2X 106491 Y7-106491 EATON ELECTRIC Cover, opening DILM4065 connection, (8unit)

Brand: EATON - MOELLER | Manufacturer Part Number: DILM65-XIP2X



Manufacturer	EATON - MOELLER
MPN / Reference	DILM65-XIP2X
Catalog number	Y7-106491
Category	Accessories/spare parts for low-voltage switch technology
Minimum order	8 Pcs
Document ID	EO-7C573BB0E1
Generated	2026-08-05

Product Overview

Cover, opening DILM4065 connection, (8unit)

DILM65-XIP2X

Eaton Moeller® series DILM Cover, connection opening DILM40-65, (8unit)

Mountable busbar tag shroud without tools

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path **EATON - MOELLER > Contactors up to 170A**

Additional Product Information

General specifications

Product Name Eaton Moeller® series DILM terminal cover Catalog Number 106491 Model Code DILM65-XIP2X EAN 4015081062607 Product Length/Depth 5 mm Product Height 25.5 mm Product Width 15 mm Product Weight 0.46 g

Certifications UL/CSA certification not required General

Accessory/spare part type Cover Product category Accessories Used with DILM80 up to DILM170 Climatic environmental conditions

Ambient operating temperature - min -25 °C Ambient operating temperature - max 60 °C Design verification

Equipment heat dissipation, current-dependent Pvid 0 W Heat dissipation capacity Pdiss 0 W Rated operational current for specified heat dissipation (In) 0 A 10.2.2 Corrosion resistance Meets the product standard's requirements. 10.2.3.1

Verification of thermal stability of enclosures Meets the product standard's requirements. 10.2.3.2 Verification of resistance of insulating materials to normal heat Meets the product standard's requirements. 10.2.3.3 Resist. of insul. mat. to abnormal

heat/fire by internal elect. effects Meets the product standard's requirements. 10.2.4 Resistance to ultra-violet (UV) radiation

Meets the product standard's requirements. 10.2.5 Lifting Does not apply, since the entire switchgear needs to be evaluated. 10.2.6 Mechanical impact Does not apply, since the entire switchgear needs to be evaluated. 10.2.7 Inscriptions Meets the product standard's requirements. 10.3 Degree of protection of assemblies Does not apply, since the entire switch...

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / DILM65-XIP2X with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.