

INDUSTRIAL COMPONENT DATA

DILM12-XP2 239370 Y7-239370 EATON ELECTRIC Paralleling link, for DIL M7-M12

Brand: EATON - MOELLER | Manufacturer Part Number: DILM12-XP2



Manufacturer	EATON - MOELLER
MPN / Reference	DILM12-XP2
Catalog number	Y7-239370
Category	Accessories/spare parts for low-voltage switch technology
Minimum order	1 Pcs
Document ID	EO-5026DABCA1
Generated	2026-08-01

Product Overview

Paralleling link, for DIL M7-M12

DILM12-XP2

Eaton Moeller® series DILM Paralleling link, for DIL M7-M12

Plug-in main current wiring bridge for quick, simple mounting

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path **EATON - MOELLER > Contactors up to 170A**

Additional Product Information

General specifications

Product Name Eaton Moeller® series DILM paralleling link Catalog Number 239370 Model Code DILM12-XP2 EAN 4015082393700 Product Length/Depth 30 mm Product Height 5.2 mm Product Width 90 mm Product Weight 0.01 kg

Certifications CSA Class No.: 3211-05

IEC/EN 60947-4-1

CSA-C22.2 No. 14-05

CE

CSA

UL 508

UL Category Control No.: NLRV

CSA File No.: 012528

UL

UL File No.: E36332 General

Accessory/spare part type Connecting bridge Product category Accessories Climatic environmental conditions

Ambient operating temperature - min -25 °C Ambient operating temperature - max 60 °C Design verification

Equipment heat dissipation, current-dependent P_{vid} 2.1 W Heat dissipation capacity P_{diss} 0 W Rated operational current

for specified heat dissipation (I_n) 22 A 10.2.2 Corrosion resistance Meets the product standard's requirements. 10.2.3.1

Verification of thermal stability of enclosures Meets the product standard's requirements. 10.2.3.2 Verification of resistance

of insulating materials to normal heat Meets the product standard's requirements. 10.2.3.3 Resist. of insul. mat. to abnormal

heat/fire by internal elect. effects Meets the product standard's requirements. 10.2.4 Resistance to ultra-violet (UV) radiation

Meets the product standard's requirements. 10.2.5 Lifting Does not apply, since the entire switchgear needs to be

evaluated. 10.2.6 Mechanical impact Does not apply, since the entire switchgear needs to be evaluated. 10.2.7 Inscriptions

Meets the product stand...

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / DILM12-XP2 with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.