

INDUSTRIAL COMPONENT DATA

DILM150-XMV50 240082 Y7-240082 EATON ELECTRIC Interlock, mechanical, for DILM80-170

Brand: EATON - MOELLER | Manufacturer Part Number: DILM150-XMV50



Manufacturer	EATON - MOELLER
MPN / Reference	DILM150-XMV50
Catalog number	Y7-240082
Category	Accessories/spare parts for low-voltage switch technology
Minimum order	1 Pcs
Document ID	EO-BC1AC2C0CD
Generated	2026-08-04

Product Overview

Interlock, mechanical, for DILM80-170

DILM150-XMV50

Eaton Moeller® series DILM Interlock, mechanical, for DILM80-150 DILM150-XMV50

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path **EATON - MOELLER > Contactors up to 170A**

Additional Product Information

General specifications

Product Name Eaton Moeller® series DILM interlock Catalog Number 240082 Model Code DILM150-XMV50 EAN 4015082400828 Product Length/Depth 125 mm Product Height 7 mm Product Width 13 mm Product Weight 0.27 kg

Certifications IEC/EN 60947-4-1

CSA Class No.: 2411-03

UL 508

CE

CSA File No.: 012528

CSA

UL

CSA-C22.2 No. 14-05

UL Category Control No.: NLDX

UL File No.: E29096 General

Accessory/spare part type Mechanical locking Product category Accessories Design verification
Equipment heat dissipation, current-dependent P_{vid} 0 W Heat dissipation capacity P_{diss} 0 W Rated operational current for specified heat dissipation (I_n) 0 A 10.2.2 Corrosion resistance Meets the product standard's requirements. 10.2.3.1 Verification of thermal stability of enclosures Meets the product standard's requirements. 10.2.3.2 Verification of resistance of insulating materials to normal heat Meets the product standard's requirements. 10.2.3.3 Resist. of insul. mat. to abnormal heat/fire by internal elect. effects Meets the product standard's requirements. 10.2.4 Resistance to ultra-violet (UV) radiation Meets the product standard's requirements. 10.2.5 Lifting Does not apply, since the entire switchgear needs to be evaluated. 10.2.6 Mechanical impact Does not apply, since the entire switchgear needs to be evaluated. 10.2.7 Inscriptions Meets the product standard's requirements. 10.3 Degree of protection of assemblies Does not apply, since the entire switchgear needs to be evaluated....

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / DILM150-XMV50 with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.