

INDUSTRIAL COMPONENT DATA

FBHMOV-80/2/03-S/A 170137 Y7-170137 EATON ELECTRIC
Residual-current circuit breaker trip block for AZ, 80A, 2..

Brand: EATON - MOELLER | Manufacturer Part Number: FBHMOV-80/2/03-S/A



Manufacturer	EATON - MOELLER
MPN / Reference	FBHMOV-80/2/03-S/A
Catalog number	Y7-170137
Category	Residual current circuit breaker (RCCB)
Minimum order	1 Pcs
Document ID	EO-21CCF493D4
Generated	2026-08-04

Product Overview

Residual-current circuit breaker trip block for AZ, 80A, 2pole, 300mA, type S/A

FBHMOV-80/2/03-S/A

Eaton Distribution parts. Residual-current circuit breaker trip block for AZ, 80A, 2pole, 300mA, type S/A

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path EATON - MOELLER > Modular Switchgear - Industrial

Additional Product Information

General specifications

Product Name Eaton Moeller series xEffect - FBHmV RCCB add-on unit Catalog Number 170137 Model Code FBHMOV-80/2/03-S/A EAN 4015081666386 Product Length/Depth 94.5 mm Product Height 80 mm Product Width 90 mm Product Weight 0.406 kg Compliances RoHS conform Certifications EN45545-2

IEC 61373

IEC/EN 60947-2 Product specifications

Type Special features Ambient temperature hint: Starting at 40 °C, the max. permissible continuous current decreases by 3% for every 1 °C Application Switchgear for industrial and advanced commercial applications

xEffect - Switchgear for industrial and advanced commercial applications

Amperage Rating 80 A Features Selective protection

Additional equipment possible

Add-on residual current protection unit 10.10 Temperature rise The panel builder is responsible for the temperature rise calculation. Eaton will provide heat dissipation data for the devices. 10.11 Short-circuit rating Is the panel builder's

responsibility. The specifications for the switchgear must be observed. 10.12 Electromagnetic compatibility Is the panel builder's responsibility. The specifications for the switchgear must be observed. 10.13 Mechanical function The device meets the requirements, provided the information in the instruction leaflet (IL) is observed. 10.2.2 Corrosion resistance Meets the product standard's requirements. 10.2.3.1 Verification of thermal stability of enclosures Meets the product standard's requirements. 10.2.3.2 Verification of resistanc...

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / FBHMV-80/2/03-S/A with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.