

INDUSTRIAL COMPONENT DATA

FBSMV-40/2/01-S/A 170158 Y7-170158 EATON ELECTRIC

Residual-current circuit breaker trip block for FAZ, 40A, ..

Brand: EATON - MOELLER | Manufacturer Part Number: FBSMV-40/2/01-S/A



Manufacturer	EATON - MOELLER
MPN / Reference	FBSMV-40/2/01-S/A
Catalog number	Y7-170158
Category	Residual current circuit breaker (RCCB)
Minimum order	1 Pcs
Document ID	EO-3CA2B79CAB
Generated	2026-08-04

Product Overview

Residual-current circuit breaker trip block for FAZ, 40A, 2pole, 100mA, type S/A

FBSMV-40/2/01-S/A

Eaton Distribution parts. Residual-current circuit breaker trip block for FAZ, 40A, 2pole, 100mA, type S/A

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path	EATON - MOELLER > Modular Switchgear - Industrial
--------------	---

Additional Product Information

General specifications

Product Name Eaton Moeller series xEffect - FBSmV RCCB add-on unit Catalog Number 170158 Model Code

FBSMV-40/2/01-S/A EAN 4015081666577 Product Length/Depth 90 mm Product Height 75 mm Product Width 70 mm

Product Weight 0.197 kg Compliances RoHS conform Certifications EN45545-2

IEC 61373

IEC/EN 61009 Product specifications

Type Special features Ambient temperature hint: Starting at 40 °C, the max. permissible continuous current decreases by 3% for every 1 °C Application Switchgear for industrial and advanced commercial applications

xEffect - Switchgear for industrial and advanced commercial applications

Amperage Rating 40 A Features Additional equipment possible

Selective protection

Add-on residual current protection unit 10.10 Temperature rise The panel builder is responsible for the temperature rise calculation. Eaton will provide heat dissipation data for the devices. 10.11 Short-circuit rating Is the panel builder's

responsibility. The specifications for the switchgear must be observed. 10.12 Electromagnetic compatibility Is the panel builder's responsibility. The specifications for the switchgear must be observed. 10.13 Mechanical function The device meets the requirements, provided the information in the instruction leaflet (IL) is observed. 10.2.2 Corrosion resistance Meets the product standard's requirements. 10.2.3.1 Verification of thermal stability of enclosures Meets the product standard's requirements. 10.2.3.2 Verification of resistance of...

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / FBSMV-40/2/01-S/A with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.