

INDUSTRIAL COMPONENT DATA

T0-3-8152/IVS 013423 Y7-13423 EATON ELECTRIC Reversing switches, Contacts: 6, 20 A, front plate: Aus-Höher 0..

Brand: EATON - MOELLER | Manufacturer Part Number: T0-3-8152/IVS



Manufacturer	EATON - MOELLER
MPN / Reference	T0-3-8152/IVS
Catalog number	Y7-13423
Category	Off-load switch
Minimum order	1 Pcs
Document ID	EO-EB49F96086
Generated	2026-08-06

Product Overview

Reversing switches, Contacts: 6, 20 A, front plate: Aus-Höher>0

Inverter switch 6 poles 20 A Indicator plate:

Eaton Moeller® series T0 Reversing switches, T0, 20 A, service distribution board mounting, 3 contact unit(s), Contacts: 6, 45 °, maintained, Aus-Höher>0

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path	EATON - MOELLER > Disconnectors and Cam Switches
--------------	--

Additional Product Information

General specifications

Product Name Eaton Moeller® series T0 Reversing switch Catalog Number 013423 Model Code T0-3-8152/IVS EAN 4015080134237 Product Length/Depth 101 mm Product Height 55 mm Product Width 54 mm Product Weight 0.155 kg

Certifications CSA-C22.2 No. 60947-4-1-14

IEC/EN 60947

VDE 0660

CE

CSA-C22.2 No. 94

UL Category Control No.: NLRV

CSA

CSA Class No.: 3211-05

IEC/EN 60204

IEC/EN 60947-3

UL

CSA File No.: 012528

UL 60947-4-1

UL File No.: E36332 Catalog Notes Rated Short-time Withstand Current (I_{cw}) for a time of 1 second

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / T0-3-8152/IVS with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.