

INDUSTRIAL COMPONENT DATA

DILP800-XMV 207474 XTCFAXMLN EATON ELECTRIC

Interlock, mechanical, for DILP800

Brand: EATON - MOELLER | Manufacturer Part Number: DILP800-XMV



Manufacturer	EATON - MOELLER
MPN / Reference	DILP800-XMV
Catalog number	XTCFAXMLN
Category	Accessories/spare parts for low-voltage switch technology
Minimum order	1 Pcs
Document ID	EO-1D12584EA4
Generated	2026-08-02

Product Overview

Interlock, mechanical, for DILP800

Mechanical Interlock For DILP800

Interlock, Product range: Accessories, Mechanical interlock, For use with: DILP500,, DILP630,, DILP800

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path EATON - MOELLER > Contactors more than 170 A

Additional Product Information

General specifications

Product Name Eaton Moeller® series DILP interlock Catalog Number 207474 Model Code DILP800-XMV EAN

4015082074746 Product Length/Depth 295 mm Product Height 46 mm Product Width 580 mm Product Weight 6 kg

Compliances CE General

Accessory/spare part type Mechanical locking Product category Accessories Climatic environmental conditions

Ambient operating temperature - min -40 °C Ambient operating temperature - max 70 °C Design verification

Equipment heat dissipation, current-dependent Pvid 0 W Heat dissipation capacity Pdiss 0 W Rated operational current for specified heat dissipation (In) 0 A 10.2.2 Corrosion resistance Meets the product standard's requirements. 10.2.3.1

Verification of thermal stability of enclosures Meets the product standard's requirements. 10.2.3.2 Verification of resistance of insulating materials to normal heat Meets the product standard's requirements. 10.2.3.3 Resist. of insul. mat. to abnormal heat/fire by internal elect. effects Meets the product standard's requirements. 10.2.4 Resistance to ultra-violet (UV) radiation

Meets the product standard's requirements. 10.2.5 Lifting Does not apply, since the entire switchgear needs to be

evaluated. 10.2.6 Mechanical impact Does not apply, since the entire switchgear needs to be evaluated. 10.2.7 Inscriptions

Meets the product standard's requirements. 10.3 Degree of protection of assemblies Does not apply, since the entire switchgear needs to be evaluated. 10.4 Clearances and creepage di...

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / DILP800-XMV with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.