

INDUSTRIAL COMPONENT DATA

DILM65-XS1 281192 Y7-281192 EATON ELECTRIC Star-point bridge, for DILM3265

Brand: EATON - MOELLER | Manufacturer Part Number: DILM65-XS1



Manufacturer	EATON - MOELLER
MPN / Reference	DILM65-XS1
Catalog number	Y7-281192
Category	Accessories/spare parts for low-voltage switch technology
Minimum order	10 Pcs
Document ID	EO-EE36B7B5A5
Generated	2026-08-03

Product Overview

Star-point bridge, for DILM3265

DILM65-XS1

Eaton Moeller® series DILM Star-point bridge, For use with DILM40 - DILM72, DILMF40 - DILMF65

Star-point bridge, Product range: Accessories, Wiring accessories, For use with: DILM40 - DILM72, DILMF40 - DILMF65

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path EATON - MOELLER > Contactors up to 170A

Additional Product Information

General specifications

Product Name Eaton Moeller® series DILM star-point bridge Catalog Number 281192 Model Code DILM65-XS1 EAN 4015082811921 Product Length/Depth 6 mm Product Height 27 mm Product Width 47 mm Product Weight 0.013 kg

Certifications CSA

CSA-C22.2 No. 14-05

UL File No.: E36332

IEC/EN 60947-4-1

CSA Class No.: 3211-04

UL

UL 508

CE

CSA File No.: 012528

UL Category Control No.: NLRV General

Accessory/spare part type Connecting bridge Product category Accessories Climatic environmental conditions

Ambient operating temperature - min -25 °C Ambient operating temperature - max 60 °C Design verification

Equipment heat dissipation, current-dependent P_{vid} 0 W Heat dissipation capacity P_{diss} 0 W Rated operational current for specified heat dissipation (I_n) 98 A 10.2.2 Corrosion resistance Meets the product standard's requirements. 10.2.3.1

Verification of thermal stability of enclosures Meets the product standard's requirements. 10.2.3.2 Verification of resistance of insulating materials to normal heat Meets the product standard's requirements. 10.2.3.3 Resist. of insul. mat. to abnormal

heat/fire by internal elect. effects Meets the product standard's requirements. 10.2.4 Resistance to ultra-violet (UV) radiation Meets the product standard's requirements. 10.2.5 Lifting Does not apply, since the entire switchgear needs to be

evaluated. 10.2.6 Mechanical impact Does not apply, since the entire switchgear needs to be evaluated. 10.2.7 Inscriptions

Meets the product standar...

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send EATON - MOELLER / DILM65-XS1 with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.