

INDUSTRIAL COMPONENT DATA

TPSA 345 FS 6364306 OBO BETTERMANN TP wall and support bracket for function maintenance, B345mm, Strip-galva..

Brand: OBO BETTERMANN | Manufacturer Part Number: TPSA 345 FS



Manufacturer	OBO BETTERMANN
MPN / Reference	TPSA 345 FS
Catalog number	6364306
Category	Bracket for cable support system
Minimum order	1 Pcs
Document ID	EO-F9CFB60C79
Generated	2026-08-02

Product Overview

TP wall and support bracket for function maintenance, B345mm, Strip-galvanised, DIN EN 10147, Steel, St
TP support / wall and support bracket FS. TP profile for use as lightweight support on horizontal concrete ceilings, on length 145-645 mm. Up to length 345 mm, the profile is used as a lightweight wall and support bracket.

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path	OBO BETTERMANN > KTS cable support systems - OBO BETTERMANN > mounting accessories
--------------	--

Additional Product Information

CO2 Footprint (GWP) Cradle-to-Gate 1,4016 kg CO2e / 1 Piece

Colour zinc

Dimension B345mm

Dimension B 60 mm

Dimension H 120 mm

Dimension L 345 mm

F in kN 0,55 kN

for width max. 300 mm

for width min. 300

Height 120 mm

Length 345 mm

Maintain electrical functions no
Material Steel
Rustproof steel, pickled no
Surface Strip galvanized
Version for Wall and support bracket
Width 60 mm

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send OBO BETTERMANN / TPSA 345 FS with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.