

INDUSTRIAL COMPONENT DATA

MSTBHK 2,5/10-G-5,08 NS32/35 1047991 PHOENIX CONTACT

Connector lanes, number of poles: 10, pitch: 5,08 mm, t..

Brand: PHOENIX CONTACT | Manufacturer Part Number: MSTBHK 2,5/10-G-5,08 NS32/35



Manufacturer	PHOENIX CONTACT
MPN / Reference	MSTBHK 2,5/10-G-5,08 NS32/35
Catalog number	1047991
Category	Feed-through terminal block
Minimum order	50 Pcs
Document ID	EO-210978608F
Generated	2026-08-06

Product Overview

Connector lanes, number of poles: 10, pitch: 5,08 mm, type of connection: Connection by screw with capsule-wheel drive, color: green, surface of contact: Tin, assembly: Lane

Rail connector, nominal section: 2.5 mm², colour: green, rated current: 12 A, dimensioning voltage (III/2): 320 V, surface contacts: Tin, contact type: Male, Number of potentials: 10, Number of rows: 1, Number of poles per row: 10, number of connections: 10, article family: MSTBHK 2.5/.. -G, pitch: 5.08 mm, connection type: Screw connection with traction capsule, mounting: Rail, conductor connection direction/printed circuit board: 0 °, Stecksystm: CLASSIC COMBICON, Lock: sin, packing type: boxed packaging

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path **PHOENIX CONTACT > PCB Connectors (PCC)**

Additional Product Information

ETIM for 1047991 Terminal blocks (EC001284)

Feature Name

Feature Value

Explosion-tested version 'Ex e' (EF008498)

No

Number of poles (EF001391)

10

Closing plate required (EF002525)

No

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send PHOENIX CONTACT / MSTBHK 2,5/10-G-5,08 NS32/35 with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.