

INDUSTRIAL COMPONENT DATA

NBC-MSD/7,0-939/FSD SCO RAIL 1452711 PHOENIX CONTACT Network cable, PROFINET CAT5 (100 MBit/s), 4-pole, halo..

Brand: PHOENIX CONTACT | Manufacturer Part Number: NBC-MSD/7,0-939/FSD SCO RAIL



Manufacturer	PHOENIX CONTACT
MPN / Reference	NBC-MSD/7,0-939/FSD SCO RAIL
Catalog number	1452711
Category	Sensor-actuator patch cord
Minimum order	50 Pcs
Document ID	EO-321497B10D
Generated	2026-07-29

Product Overview

Network cable, PROFINET CAT5 (100 MBit/s), 4-pole, halogen-free PE-X, black, shielded, cable length: 7 m, Customer variant

Network cable

STRUCTURED PRODUCT DATA

Technical Specifications

No structured technical attributes are currently available. Submit an RFQ for technical review.

Classification & Catalog Path

Catalog path	PHOENIX CONTACT > Industrial Field Connectivity (IFC)
--------------	---

Additional Product Information

ETIM for 1452711 Sensors (EC001855)

Feature Name

Feature Value

Number of poles (EF001391)

4

Cable length (EF000536)

7 m

Material of cable sheath (EF004136)

Other

Halogen free (EF000025)

Yes

Colour cable sheath (EF008249)

Black

With LED indication (EF005950)

No

Screened (EF000881)

Yes

Vulcanize (EF004115)

No

Material contact body (EF008248)

Other

Material of contact surface (EF004020)

Other

Permitted cable outer temperature after assembling without vibration (EF001686)

-40 °C

Permitted cable outer temperature during assembling/handling (EF001685)

-25 °C

Rated current In (EF008250)

4 A

Rated voltage (EF000228)

48 V

REQUEST PRICE, AVAILABILITY & TECHNICAL REVIEW

Send PHOENIX CONTACT / NBC-MSD/7,0-939/FSD SCO RAIL with the required quantity to info@electricaonline.com or use electricaonline.com/request-quote.

GLOBAL OFFICES

Germany: Lise-Meitner-Straße 13, 89081 Ulm | USA: 16225 Park Ten Pl #500, Houston, TX 77084 | UAE: HDS Business Centre Tower, Cluster M, 33rd Floor, JLT, Dubai

Catalog-generated document. Product names, marks and specifications belong to their respective owners. Verify safety-critical, compatibility and certification requirements against the manufacturer documentation before purchase or installation.